



# COLLECTION SYSTEMS COMMITTEE MEETING

## Trenchless Mechanical Spot Repairs

*Tuesday – March 29, 2016 – Irvine, Ca.*

***Presented by: Dave Badgley – Badgley & Assoc.***

***Representative for:***

Pipeline Rehab.

Maintenance Hole Rehab.

Odor Control



# What we are going to cover

- Where Can Spot Repairs be Used
- Pipeline Problems
- Evolution of sewer spot repair technology
- Large Diameter (Man Entry) Pipelines 18 & Larger
- Small Diameter (Robotic Access) Pipelines 8-24
  - Spot repairs
  - Offset sealing
  - Pipeliner end seals
- External pipeline repairs

# Dig & Replace Applications



Deteriorated Bottoms



Protruding Laterals



Severe Offsets over  $\frac{3}{4}$ "






Crushed Pipe



Gas Line Bored Trough



# Traditional Dig & Replace Problems



# Dig & Replace

## Advantages


- Structural Repair / damaged section only
- Correct misalignments

## ➤ Disadvantages

- High cost
- Access limitations
- Roots may grow back
- Disruptive
  - Traffic
  - Private property damage
  - Can lead to Unlimited costs – Change orders




# Trenchless Spot Repair Applications



Coating Failures



Bored Gas Lines



Capped Lateral Connections



Infiltration



Liner Failures



Mineral Deposits



Offsets <math>< 3/4''</math>




Holes

# Classic Pipe Joints

Top of Pipe Joint Grouted



Tar Joints



Grout in joint




Bottom of pipe joint  
No grout



PVC Joint - 1960

# Infiltration Cost Savings

Treatment Cost **\$1.00 per 1000 Gallons** of Water



Leak Rate	Gallons Per Day	Annual Cost 1 Joint	Annual Cost 5 Joints	Annual cost 10 Joints
1 GPM	1,440	\$526.00	\$2,628.00	\$5,260.00
<b>5 GPM</b>	<b>7,200</b>	<b>\$2,628.00</b>	<b>\$13,140.00</b>	<b>\$26,280.00</b>
10 GPM	14,400	\$5,256.00	\$26,280.00	\$52,560.00
20 GPM	28,800	\$10,512.00	\$52,560.00	\$105,120.00



# Water Loss - Leaking joints

## EPA Report



### WATER AUDITS AND WATER LOSS CONTROL FOR PUBLIC WATER SYSTEMS


#### The Water Loss Problem

Public water systems face a number of challenges including aging infrastructure, increasing regulatory requirements, water quantity and quality concerns and inadequate resources. These challenges may be magnified by changes in population and local climate. It has been estimated that:

- The United States will need to spend up to \$200 billion dollars on water systems over the next 20 years to upgrade transmission and distribution systems.<sup>i</sup>
- Of this amount, \$97 billion (29 percent) is estimated to be needed for water loss control.<sup>ii</sup>
- Average water loss in systems is 16 percent - up to 75 percent of that is recoverable.<sup>ii</sup>

***Average Water Loss is 16% - up to 75% of that is recoverable***

# History of Trenchless Pipeline Rehabilitation

- **1960 Chemical Grouting**
  - **1970 Continuous HDPE Sliplining**
  - **1980 Cured-in-Place**
  - **1990 Segmented Sliplining**
  - **1990 Folded-and Reformed**
- 


# Trenchless Spot Repairs

- ***Chemical Joint Sealing***
- ***Mechanical Spot Repairs first generation***
- ***CIPP Trenchless Spot Repair***
- ***Mechanical Trenchless Next generation***
  - ***Large Diameter 18 – 180 inch***
  - ***Small diameter 6 - 18 Inch***



# 1976 Large Diameter 18" & Larger

## INTERNAL SEALS





TECH-O-LEAS  
TECHNOLOGY

# Large Diameter Internal Joint Seal

## For open Joints & failing coatings

- A mechanical system that seals across open joints to prevent leaks or eliminate infiltration at pipe joints



# Installation of Internal Joint Seals



**Rubber Seal**



**Installation Tool**



**Installation**



**Installed Seals**







# Evaluation of Spot Repair Systems

1960

1980

1993

2004




**Inversion Style  
CIPP Felt  
Polyester Resin**

**Burrito Wrap Style  
Fiberglass  
Silicate Resin**



**Burrito Wrap Style  
Fiberglass & Epoxy**



# Small Diameter Spot Repairs





Spot Repair





Offset Repair



Pipe Liner End Seal




# Pipe-Seal-Fix





# Infiltration



Pre lining 10:05



Post lining 12:47

# Pipe Liner End Seals



**End seal not installed**





**Poor Quality Workmanship**





# Mechanical End Seals



Pipe-Seal End 8" – 32"

Large Diameter 18" and Larger



# Pipe-Seal-Flex

Corrects misaligned and off-set joints 8 - 18





# EPA Emerging Technology



**North American Society for Trenchless Technology (NASTT)  
NASTT's 2016 No-Dig Show**



**Dallas, Texas  
March 20-24, 2016**

**WM-T2-04**

## **Testing and Performance Evaluation of an Internal Pipe Sealing System**

Shaurav Alam, Trenchless Technology Center, Ruston, LA  
Wendy Condit, Battelle, Columbus, OH  
John Matthews, Pure Technologies, Baton Rouge, LA  
Ariamalar Selvakumar, U.S. EPA, Edison, NJ

# Field Testing



Figure 3. Installation at the Downstream Manhole



Figure 4. Manual Plug Inflation

# Lab Testing




Figure 8. Test Setup – Positioning the Sample and Tube Inside a Larger Diameter Pipe

Water pressure was applied on the specimens and the specimens were found to hold 15 psi pressure (which is twice the design pressure) for approximately 150 minutes each with no leaks observed. For Specimens #1 and #2, minor leaks were found around the inflatable tubes that were part of the testing apparatus, which were regulated by increasing the water supply pressure. No leaks were observed in the inflatable tubes for the Specimen #3 indicating optimization of the test setup (see the constant pressure achieved in Specimen 3 in Figure 9). Next, Specimen #2 was prepared for an external hydraulic test that would take the seal to failure conditions in order to determine the maximum external hydraulic pressure. The seal broke at approximately 65 psi, although it is designed for 7.25 psi (see Figure 10).

## 5. TECHNOLOGY EVALUATION

In addition to the field demonstration, the system was also tested in the laboratory through the ability of the seal to resist external hydrostatic pressure on three test pipes consisting of 8-in diameter, unlined steel. The tests conducted did not simulate applying the sleeve over a defect in CIPP lined pipe, which could be a consideration for further study. Steel mechanical tubes were cut into 12-inch by 8-inch pieces and then tack welded simulating a crack or defect that spanned the circumference of the pipe. The resulting gaps were measured around the circumference of the pipe and averaged 0.25, 0.32, and 0.34 inches for pipes 1, 2, and 3, respectively (Figure 6). The repair was then performed on each of the three pipes and subjected to external hydraulic testing up to 15 psi. In addition, one specimen was taken to failure to observe the maximum external pressure that could be withstood.



Figure 6. Measurement of the Annular Gaps




# Conclusion

## 6. CONCLUSION


The laboratory evaluation of the internal pipe sealing system verified an external pressure of 15 psi was withstood with no leaks (approximately twice the design pressure of 7.25 psi) over 2.5 hours. The field demonstration of the internal pipe sealing system encountered some challenges, which prevented the robotic installation aspect of the technology from being fully observed. The issues were primarily related to access issues for the packer system in the pipe which had an offset in the CIPP-lined host pipe downstream. Also the limited size of the manhole upstream resulted in the need for the seal to be manually placed. The installation was completed in approximately three hours from site preparation to final CCTV inspection. The project had a negligible carbon footprint as the equipment required for the installation was minimal. The technology shows promise as a low-cost and rapid trenchless repair approach. However, access requirements should be assessed based upon site-specific conditions to ensure feasibility of the robotic-assisted installation, especially in previously lined pipes. If possible, the initial CCTV inspection should be completed with the packer assembly and/or a simulated pig of similar dimensions to ensure that bends and offsets can be successfully navigated.



# Video Training Graphic



# Infiltration Test Installation 1:07



# Questions or Comments?

- ***Dave Badgley***
- ***Badgley & Assoc.***
- Direct Phone: (818) 843-3318
- Direct Fax: (818) 843-7021
- Email: [DBadge@Aol.com](mailto:DBadge@Aol.com)

Pipeline Rehab.



Maintenance  
Hole Rehab.



Odor Control

